

HISTORIC AMERICAN BUILDINGS SURVEY  
INDEX TO PHOTOGRAPHS

HABS  
GA,  
61-ATLA,  
12-

Carnegie Library of Atlanta (Atlanta Public Library)  
126 Carnegie Way  
Atlanta  
Fulton County  
Georgia

HABS No. GA-1216

David J. Kaminsky, Photographer      December, 1976

- GA-1216-1      EASTERN HALF OF NORTH FRONT
- GA-1216-2      WESTERN HALF OF NORTH FRONT
- GA-1216-3      NORTH FRONT AND EAST SIDE
- GA-1216-4      EAST SIDE
- GA-1216-5      1950 ADDITION TO WEST END
- GA-1216-6      NORTH FRONT, ENTRANCE AND FLANKING WINDOWS
- GA-1216-7      NORTH FRONT, ENTRANCE AND WINDOWS TO WEST
- GA-1216-8      NORTH FRONT, DETAIL OF FIRST STORY WINDOW
- GA-1216-9      NORTH FRONT, DETAIL OF DECORATION ABOVE ENTRANCE
- GA-1216-10      NORTH FRONT, DETAIL OF COLUMNS AND ENTABLATURE
- GA-1216-11      NORTH FRONT, DETAIL OF COLUMN CAPITALS AND ENTABLATURE
- GA-1216-12      INTERIOR, MAIN ENTRANCEWAY
- GA-1216-13      INTERIOR, FIRST FLOOR, EAST READING ROOM, SOUTHEAST CORNER
- GA-1216-14      INTERIOR, FIRST FLOOR, WEST READING ROOM, LOOKING SOUTH
- GA-1216-15      INTERIOR, BASEMENT, EAST READING ROOM, ELEVATION OF "UNCLE REMUS" MANTLE
- GA-1216-16      INTERIOR, BASEMENT, EAST READING ROOM, OBLIQUE VIEW OF "UNCLE REMUS" MANTLE
- GA-1216-17      INTERIOR, BASEMENT, EAST READING ROOM, "UNCLE REMUS" MANTLE, DETAIL OF MANTLE TILES
- GA-1216-18      INTERIOR, ROOF TRUSSES, LOOKING TOWARD NORTHEAST
- GA-1216-19      INTERIOR, ROOF TRUSSES, DETAIL, LOOKING EAST
- GA-1216-20      Photocopy of photograph, circa 1903  
INTERIOR, MAIN ENTRANCEWAY PRIOR TO ALTERATION

GA-1216-21      Photocopy of photograph, circa 1903  
INTERIOR, REFERENCE READING ROOM